

NPA 05/12

SUBJECT: AP0059 Fuel Return Line Banjo Bolt

April 12, 2012

Alliant Power is pleased to announce the release of the **AP0059** Fuel Return Line Banjo Bolt for the 6.6 L LB7 Duramax[®]. Removal of the banjo bolts are required when servicing the fuel injectors. During the removal process, the hex drive is prone to damage which can make it difficult to torque properly during reassembly. Applying improper torque to the banjo bolt can lead to fuel leaks and crankcase dilution (fuel in oil). Alliant Power recommends replacing damaged banjo bolts to assure proper torque.



AP PART NUMBER	YEAR RANGE	APPLICATION	OEM PART NUMBER
AP0059	2001–2004½	6.6 L LB7 Duramax	97228929



New Product Announcement