

NPA 07/11

**SUBJECT: Remanufactured G2.9 Injectors at New Reduced Pricing
July, 2011**

Alliant Power is pleased to offer Remanufactured G2.9 Injectors at new reduced pricing. The process uses proven technologies and techniques acquired from the G2.8 remanufacturing process. Each unit is 100% flow tested to ensure product operation and durability.



AP G2.9 injectors are identified by the part number on the body.

AP PART NUMBER	YEAR RANGE	APPLICATION	ESN RANGE	OEM PART NUMBER
AP66976	2004	DT466: 210 HP to 225 HP	2,000,001 to 2,999,999	1842576C93 5010656R92 1841491C91 1842223C1
AP66977	2004	DT466: 245 HP to 285 HP (HT)	2,000,001 to 2,999,999	1842577C93 5010657R92 1842224C91
	2005	DT466: 210 HP to 285 HP		
AP66978	2004–2005	DT570: 285 HP to 330 HP	2,000,001 to 2,999,999	1842578C94 5010658R92 1842225C91
AP66979	2004–2005	HT570: 295 HP to 340 HP (HT)	2,000,001 to 2,999,999	1842579C94 5010659R92 1842226C91

Note: The new part numbers supersede the previous part numbers with the number "8" (AP668XX).

Installation Information:

Replacement of G2.9 Injectors requires removal of the high–pressure oil rail. The injector inlet seals are incorporated on the oil rail and must be replaced prior to reinstalling. Alliant Power kit **AP0025** will provide the necessary seals and backup rings to reseal the rail properly.

All new products are backed with Alliant Power's 13–month, unlimited mileage warranty, as well as Alliant Power's technical support.



New Product Announcement