

## TECHNICAL BULLETIN APTB 02/10 ■ Feb 2010

## SUBJECT: Return of No-Fault Found Injectors | R-1







Alliant Power diagnoses all components submitted for warranty consideration. For a variety of reasons, some injectors submitted for warranty are diagnosed as no-fault found (NFF). Similar to most other manufacturers or remanufacturers with limited warranty policies, components determined by Alliant Power to be NFF are returned to the submitting Service Dealer.

To comply with ISO standards regarding identification of previously installed components, effective March 29, 2010, Alliant Power placed a sticker on NFF injector boxes identifying them as previously installed products (refer to photos above).

Please note Alliant Power verifies that NFF injectors meet 0EM performance specifications. Our standard 13-month, unlimited mileage warranty also applies to NFF products.

R1-Removed "both 7.3L HEUI and 6.0L"

For more information visit