

SUBJECT: Remanufactured Diesel Particulate Filter (DPF) Program

Alliant Power is pleased to announce the release of our Remanufactured Diesel Particulate Filter (DPF) Program for the applications listed in the table. These products are remanufactured by our OEM partner using their patented multi-step OEM approved remanufacturing process. This process is vastly superior to in-field cleaning machines removing up to 55% more ash restoring the DPF back to like new condition. This ensures the end customer achieves maximum service life, fuel economy and engine performance. DPFs include the necessary gaskets for installation. DPF clamps and gaskets are also available separately, see [NPA 02/19](#) for further details. DPFs ship direct from our OEM partner where standard ground outbound, as well as core return shipping, are included in the price. Expedited shipping is available at an incremental \$150.00 USD flat rate.

All new products are backed with Alliant Power's 13-month, unlimited mileage warranty, as well as Alliant Power's technical support. Not available for sale or use in California.



For more information visit
AlliantPower.com

Application information		Alliant Power part numbers			OEM cross referencing
Engine make	Engine models ⁸	Diesel particulate filter (DPF) ¹	DPF gasket ²	DPF clamp ³	Diesel particulate filter (DPF)
Cummins®	ISX	AP70100	AP70300 (2)	AP70400 (2)	2871581RX
	ISX	AP70101	AP70300 (2)	AP70400 (2)	4388409
	ISX	AP70102	AP70300 (2)	AP70400 (2)	5295609RX
	ISX	AP70103	AP70300 (2)	AP70400 (2)	2871578RX
	ISX	AP70104	AP70300 (2)	AP70400 (2)	5295604RX
	ISL, ISM	AP70105	AP70300 (2)	AP70400 (2)	4352923
	ISX	AP70106	AP70300 (2)	AP70400 (2)	4388411
	ISL, ISM	AP70107	AP70300 (2)	AP70400 (2)	4352920
	ISC	AP70108	AP70301 (2)	AP70401 (2)	4969838
	ISB	AP70109	AP70302 (2)	AP70402 (2)	4965287
	ISB	AP70124	AP70302 (2)	AP70402 (2)	2871462RX
	ISL	AP70125	AP70301 (2)	AP70401 (2)	2871463RX
Navistar®	MaxxForce 7	AP70110 ⁴	AP70303 inlet (1) AP70304 outlet (1)	Not applicable	Call AP Technical for fit ⁴
	MaxxForce DT / 9 / 10	AP70111 ⁴	AP70303 inlet (1) AP70304 outlet (1)	Not applicable	Call AP Technical for fit ⁴
	MaxxForce DT / 9 / 10	AP70112 ⁴	AP70305 (2)	AP70403 (2)	Call AP Technical for fit ⁴
	MaxxForce 13	AP70113 ⁷	AP70306 ⁷ tape (1)	AP70404 (2)	5010844RI, 2604823C9I
	MaxxForce 11 / 13	AP70114 ⁷	AP70306 ⁷ tape (1)	AP70404 (2)	5010845RI, 2604830C9I
	MaxxForce 7 / DT	AP70127 ⁴	AP70303 inlet (1) AP70304 outlet (1)	Not applicable	Call AP Technical for fit ⁴
	MaxxForce DT / 9 / 10	AP70128 ⁴	AP70303 inlet (1) AP70304 outlet (1)	Not applicable	Call AP Technical for fit ⁴
	MaxxForce DT / 9 / 10	AP70129 ⁴	AP70305 (2)	AP70403 (2)	Call AP Technical for fit ⁴
	MaxxForce 7 / DT / 9 / 10	AP70130 ⁴	AP70305 (2)	AP70403 (2)	Call AP Technical for fit ⁴
Detroit™ Diesel	Series 60	AP70115	AP70307 (2)	AP70405 (2)	RA6804908692
	DD13, DD15, DD16	AP70116 ⁵	AP70308 ⁵ inlet (1)	AP70406 inlet (1) AP70407 ^{5,6} outlet (1)	RA0004903792
Mercedes-Benz®	MBE 4000, OM460, OM926	AP70117	AP70309 (2)	Not applicable	RA6804908792
Volvo®, Mack®	D13, MP8	AP70118	AP70310 (2)	AP70408 (2)	22810502
	D11, D13, D16	AP70119	AP70311 (2)	AP70409 (2)	21850658
	MP7	AP70120	AP70312 (2)	AP70410 (2)	20231111
	MP7, MP8, D11, D13	AP70126	AP70312 (2)	AP70410 (2)	22761989
Caterpillar®	C13, C15	AP70121	AP70313 (2)	AP70411 (2)	10R6089
	C9, C13, C15, C16	AP70122	AP70314 (2)	AP70412 (2)	10R6088
	C7	AP70123	AP70315 (2)	AP70413 (2)	10R6082

¹ Associated DPF inlet and outlet gaskets are included with remanufactured DPF. Gaskets and clamps also available separately. See [NPA 02/19](#).

² Alliant Power DPF gaskets are included with DPF and are also sold individually. Quantity indicated in parentheses next to the part number is the required gaskets for that particular application. Gaskets fit inlet and outlet unless otherwise noted.

³ Alliant Power DPF clamps are sold individually and are not included with DPF. Quantity indicated in parentheses next to the part number is the required clamps for that particular application. Clamps fit inlet and outlet unless otherwise noted.

⁴ Contact Alliant Power Technical at **1.800.735.9775** for assistance determining correct DPF. VIN and ECM calibration required. See [APT 01/19](#).

⁵ AP70116 DPF includes AP70308 inlet gasket and AP70407 outlet clamp with incorporated gasket.

⁶ AP70407 outlet clamp includes the outlet gasket which is incorporated into the clamp.

⁷ AP70113 and AP70114 DPFs include AP70306 gasket tape.

⁸ Information is reference only. Contact Alliant Power Technical **1.800.735.9775** to verify part application.

For more information visit
AlliantPower.com

Alliant Power Technical Support: 800.735.9775 | techsupport@AlliantPower.com

©2019 Diesel Forward, Inc