


NPA 05/13
SUBJECT: AP66918, AP66921 & AP66989
Remanufactured G2.9 Injectors
June 27, 2013



Alliant Power is pleased to offer the below Remanufactured G2.9 Injectors at new reduced pricing. The process uses proven technologies and techniques acquired from the G2.8 remanufacturing process. Each unit is 100% flow tested to ensure product operation and durability.

Installation Information:

Replacement of G2.9 Injectors requires removal of the high-pressure oil rail. The injector inlet seals are incorporated on the oil rail and must be replaced prior to reinstalling. Alliant Power kit **AP0025** will provide the necessary seals and backup rings to reseal the rail properly.

AP G2.9 injectors are identified by the part number on the body.

All new products are backed with Alliant Power's 13-month, unlimited mileage warranty, as well as Alliant Power's technical support.

| AP PART NUMBER | OBSOLETE AP PART NUMBER | YEAR RANGE | APPLICATION | ESN RANGE | OEM PART NUMBER |
|----------------|-------------------------|------------|---------------------------------|------------------------|--------------------------|
| AP66918 | AP66818 | 2007–2010 | MaxxForce® DT: 210 HP to 300 HP | 3,000,001 to 3,300,000 | 1848718C92 5010561R91 |
| AP66921 | AP66821 | 2007–2010 | MaxxForce 9: 300 HP to 330 HP | 3,000,001 to 3,300,000 | 1848721C92 4307212R91 |
| | | | MaxxForce 10: 310 HP to 350 HP | | |
| AP66989 | AP66889 | 2006 | DT466: 210 HP to 285 HP (BANG) | N/A | 1848489C91 |



New Product Announcement