

## NEW PRODUCT NPA 11/19 ► October 9, 2019

## SUBJECT: Alliant Power 100% New Diesel Particulate Filters

Alliant Power is pleased to announce the release of 33 New Diesel Particulate Filters (DPF) for the applications listed in the table on the back. Each DPF has 100% brand new OEM-quality filter substrate and housings. While there is no core charge, Alliant Power does offer complementary core recycling.

DPF clamps and gaskets are also available separately, see NPA 02/19 for further details.

All New DPFs are backed by Alliant Power's 36-month, unlimited mileage warranty, as well as Alliant Power's technical support.



Product photographed for reference only. Each component sold separately.


Not for sale or use in California.

New DPFs, Gaskets and Clamps							
Application i	nformation	Alli	iant Power part	number	OEM cross referencing		
Engine make	Engine models	DPF <sup>1</sup>	DPF gasket <sup>2</sup>	DPF clamp <sup>3</sup>	DPF	DPF gasket	DPF clamp
Cummins <sup>®</sup>	ISX	AP70200	AP70300 (2)	AP70400 (2)	2871581RX	2871453	2871863
		AP70201			4388409		
		AP70202			5295609RX		
		AP70203			2871578RX		
		AP70204			5295604RX		
		AP70206			4388411		
	ISL, ISM	AP70205			4352923		
		AP70207			4352920		
	ISC	AP70208	AP70301 (2)	AP70401 (2)	4969838	2871452	2871862
	ISL	AP70225			2871463RX		
	ISX	AP70232			5295605RX		
	ISB	AP70209	AP70302 (2)	AP70402 (2)	4965287	2871451	2871861
		AP70224			2871462RX		
		AP70231			5295603RX		
Navistar®	MaxxForce® 7	AP70210 <sup>4</sup>	AP70303 inlet (1) AP70304 outlet (1)	Not applicable	Call AP Technical For Fit*  2593981C91, 5010836R91, 2604873C91,	2593998C1 inlet 2593986C1 outlet	Not applicable
	MaxxForce DT/9/10	AP70211 <sup>4</sup>					
		AP70228 <sup>4</sup>					
	MaxxForce 7 / DT	AP70227 <sup>4</sup>			5010847R1, 2594356C91, 5010834R91, 2611630C91,		
	MaxxForce DT/9/10	AP70212 <sup>4</sup>	AP70305 (2)	AP70403 (2)	5010852R1, 2594165C91, 5010830R91, 2594131C91, 5010832R91, 2612521C91,		2594128C1
		AP70229 <sup>4</sup>			5010853R1, 2605837C1, 5010850R1	2594129C1	
	MaxxForce 7/DT/9/10	AP70230 <sup>4</sup>					
	MaxxForce 13	AP70213 <sup>7</sup>	A DE0706 1 /1)		5010844R1, 2604823C91	2604051C91 tape	FLTXC138PS
	MaxxForce 11 / 13	AP70214 <sup>7</sup>	AP70306 tape (1)	AP70404 (2)	5010845R1, 2604830C91		
Detroit™ Diesel	Series 60®	AP70215	AP70307 (2)	AP70405 (2)	RA6804908692	A4709970045	A4709950002
	DD13, DD15, DD16	AP70216 <sup>5</sup>	AP70308 <sup>5</sup> inlet (1)	AP70406 inlet (1)	RA0004903792	A6804910480 inlet	A6809950202 inlet
				AP70407 <sup>5, 6</sup> outlet (1)			A6809950302 outlet
Mercedes-Benz®	MBE 4000, OM460, OM926	AP70217	AP70309 (2)	Not applicable	RA6804908792	A6804910180	Not applicable
Volvo <sup>™</sup> /Mack®	D13, MP8	AP70218	AP70310 (2)	AP70408 (2)	22810502	21212522	21212520
	D11, D13, D16	AP70219	AP70311 (2)	AP70409 (2)	21850658	21371339	21445458
	MP7	AP70220	AP70312 (2)	AP70410 (2)	20231111	21048511	21048521
	MP7, MP8, D11, D13	AP70226	AP70312 (2)	AP70410 (2)	22761989	21048511	21048521
Caterpillar®	C13, C15	AP70221	AP70313 (2)	AP70411 (2)	10R6089	278-5711	278-5712
	C9, C13, C15, C16	AP70222	AP70314 (2)	AP70412 (2)	10R6088	279-2123	279-2124
	C7	AP70223	AP70315 (2)	AP70413 (2)	10R6082	279-3259	279-3260

<sup>&</sup>lt;sup>1</sup> Associated DPF inlet and outlet gaskets are included with DPF. Gaskets and clamps also available separately.

Information is reference only. Contact Alliant Power Technical Support to verify part application.







<sup>&</sup>lt;sup>2</sup> Alliant Power DPF gaskets are included with DPF and are also sold individually. Quantity indicated in parentheses next to the part number is the required gaskets for that particular application.

<sup>&</sup>lt;sup>3</sup> Alliant Power DPF clamps are sold individually and are not included with DPF. Quantity indicated in parentheses next to the part number is the required clamps for that particular application. <sup>4</sup> Call Alliant Power Technical for assistance determining correct DPF. VIN and ECM calibration required. See <u>APTB 01/19</u>.

Call Alliant Power Technical for assistance determining correct DPF. VIN and ECM calibration required. See <u>APTB 01/1</u>
 AP70216 DPF includes AP70308 inlet gasket and AP70407 outlet clamp with incorporated gasket.

<sup>&</sup>lt;sup>6</sup> AP70407 outlet clamp includes the outlet gasket which is incorporated into the clamp.

<sup>&</sup>lt;sup>7</sup> AP70213 and AP70214 DPFs include AP70306 gasket tape.